

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
15-FACR,
1-

Carvill Hall
Fairlee Creek
Kent County
Maryland

HABS No. MD-867

Randolph Langenbach, Photographer 1973

- MD-867-1 WEST ELEVATION
- MD-867-2 WEST ELEVATION, DETAIL OF ENTRANCE (NOTE SCARS LEFT BY REMOVAL OF PORCH)
- MD-867-3 PERSPECTIVE VIEW OF NORTH AND EAST ELEVATIONS
- MD-867-4 NORTH ELEVATION, SHOWING PROJECTING CHIMNEY AND WINDOWS IN GABLE
- MD-867-5 GROUND FLOOR, STAIRHALL, TAKEN FROM EAST
- MD-867-6 SECOND FLOOR, NORTH ROOM, VIEW TOWARD FIREPLACE, SHOWING BEAMED CEILING
- MD-867-7 SECOND FLOOR, VIEW LOOKING INTO SOUTH ROOM
- MD-867-8 CELLAR, NORTH WALL, SHOWING BASE TO FORMER CENTRAL CHIMNEY (NOW A LAUNDRY AREA)
- MD-867-9 CELLAR, NORTH WALL, VIEW LOOKING UP TO BASE OF FORMER CHIMNEY
- MD-867-10 CELLAR, NORTH WALL, VIEW LOOKING UP TO BASE OF FORMER CENTRAL CHIMNEY
- MD-867-11 ATTIC, STAIRS, VIEW SHOWING BLOCKED OPENING TO FORMER PORCH TOWER
- MD-867-12 ATTIC, STAIRS, DETAIL OF BLOCKED OPENING TO FORMER PORCH TOWER
- MD-867-13 ATTIC, ROOM, DETAIL OF WINDBRACE
- MD-867-14 DETAIL OF ROOF FRAME
- MD-867-15 ROOF FRAME, DETAIL SHOWING PURLIN NOTCHED TO ACCOMODATE FORMER CENTRAL CHIMNEY STACK